Tor Edition

31 October 1967

of the s

MEMORANDUM FOR: Director of Central Intelligence

SUBJECT : CXCART Operations on 27, 28, 29 October (local time)

- 1. This memorandum is for your information.
- 2. Since deployment of the OKCART aircraft to Endens Air Base, Chinava, we have flown 18 photographic missions over North Viet Ham. Of these, 7 were flown during the month of October, 3 of which were on successive days over last weekend.
- 3. Beginning with the third mission the Chinese and later North Vietnamese Air Defense Radar networks have tracked the sireraft and have steadily improved their tracking capability. In the past several attempts to launch a SA-3 missile at the aircraft have been made but the first actual launches occurred over last weekend. One such attempt occurred on Friday might (local time) and there were probably at least 5 missiles launched against Sunday might's mission. One from the Rep Air Field area and 4 from the Manoi. It will be several days before we complete our detailed analysis of this activity but the following preliminary facts have been established:
 - a. Buring the period when SA-2 missiles were being launched the aircraft

WE 0172-67

copy of

was flying in excess of mock 3.1 and at altitudes varying from about 83,000 to 85,000 feet.

- b. Our jammer systems about the aircraft appeared to function normally and may have played a key role in preventing a sheet down.
- c. The pilot actually observed 4 missiles of which 3 appeared to burst behind but fairly close to the aircraft.
- d. After landing an inspection revealed a small hole in the bettem of the aircraft which penetrated three layers of titanium notal and the metal object was actually found inside one of the fuel tanks. The fragment is being returned to the 35 for analysis but we would presume at this point it is in fact a fragment of a SA-2 warhead.
- e. COMINT confirms the launches as observed by the pilet and indicates that the launch cross thought that 3 of the missiles performed properly.
- 4. We are obviously concerned about the safety of the aircraft and will theroughly review all the information before making final recommendations. For the moment, however, we do not believe that there is sufficient concern to warrant a stand-down and would propose that if the weather clears that we should continue to operate with a number of procentions such as maintaining very high altitude and some adjustment of our flight routes. We will make further recommendations concerning any other adjustments in the program that may be required when our analysis is complete.

CARL R. BUCKETT Deputy Director for

Science and Technology

Distribution:

cy 1 & 2 - DCI

cy 3 - IR

cy 4 - DD/SMT chrone

CY 5 - 08A

cy 6 & 7 - SMT Reg

Originator: Duckett:ab

BYE 0172-67

copy of

page 2